



INSPECTION LOCATION: WOODWARD AVE WASTE WATER TREATMENT PLANT 700 WOODWARD AVE HAMILTON L8H 6P4 INSPECTION CUSTOMER: CITY OF HAMILTON 71 MAIN ST W 4TH FLOOR HAMILTON L8P 4Y5	INSPECTION DETAILS Date of Inspection: Inspector was not onsite Total Hours: .75 (Travel time not included) Type: Follow Up Inspection (Operating Engineers) Reference No.: R-965
Inspection report delivered by email: CITY OF HAMILTON(chris.olszewski@hamilton.ca)	

INSPECTION NOTES Inspection order(s) are issued pursuant to my authority under section 21. (1) of the Technical Standard and Safety Act, 2000.
--

ISSUED INSPECTION ORDER(S) TO: CITY OF HAMILTON			
No.	Inspection Order(s)	Issued Date	Compliance Date
1	Technical Standards and Safety Act 2000 21 The safety valves on the equipment noted below are not less than 5 years old and shall be recertified by a certified safety valve agent, or be replaced. safety valve on compressor by boiler room dated 2011, expired, please replace. Please check other compressed air systems for date	Sep 25, 2020	Jan 15, 2021

This report is issued under the *Technical Standards and Safety Authority Act, 2000, s. 17 (1)*

17. (1) An inspector may conduct an inspection and may, as part of that inspection, enter and inspect at any reasonable time the lands and premises where any of the things, parts of things or classes of things to which this Act, the regulations or a Minister's order apply are used, operated, installed, made, manufactured, repaired, renovated or offered for sale for the purpose of,
(a) ensuring compliance with this Act, the regulations or a Minister's order;
(b) ensuring that an authorization holder remains entitled to the authorization; or
(c) determining whether a hazardous condition exists. 2006, c. 34, s. 25 (5).

As a not-for-profit regulatory authority, TSSA operates on a cost recovery basis.